GLENCORE

Unplanned initiation Clermont 24th November 2017

Location

Clermont Coal is a thermal coal mine located in the Wolfang Basin, west of the Bowen Basin some 16 kilometres by road, to the north of the township of Clermont.



Geology

- Wolfang Basin is an elongate, north-south trending lower Permian sedimentary basin, approx 5km long by 1.5km wide.
- Developed on a basement of metamorphics & overlain by tertiary basalt flows & sediments.
- The Strata is truncated on the western side.





Incident Location





Approximate location of incident

Incident Description

Date & Time of Incident:	24 Nov 2017 at 2030 hrs
Location:	Clermont Coal
Incident Summary:	Unplanned initiation of blast hole E2 on pattern P16-158-01T
Persons Injured:	Nil

Description:

- On the 24th November 2017 at 8:30pm an unplanned initiation of blast hole No. E2 on pattern P16-158-01T occurred.
- There was no work being undertaken on the blast pattern at the time of the incident, and the initiation was not witnessed by any individuals.
- The exact timing of the initiation is known as it registered on the sites blast noise and vibration monitoring system.
- The incident was discovered during a routine inspection of the area by three supervisors at approximately 11:15pm that evening.
- Emergency procedures were enacted and the investigation team mobilised.

GLENCORE 5

Key Events

- **1.** 17/11/17
 - Drilling The first holes drilled were 8 holes to be gamma logged
 - Hole D3 was drilled to a depth of ~54m until it intersected both the smaller upper coal seams in our pit (Gowrie and Prospect seams)

2. 20/11/17

- Hole E2 was drilled to a depth of 17m and no coal was intersected
- Hole D3 was Gamma logged

3. 22/11/17

• Hole D3 was backfilled to a depth of ~17m with coal stemming on nightshift

4. 23/11/17

- At 1:30pm a Shotfirer performing dewatering duties on the pattern noticed white smoke and a smell coming from near the collar of hole D3.
- The pattern was evacuated and a watercart used to spray water on the affected area to cool it down.
- Inspection of the area indicated that there was coal stemming / cuttings and explosive product around the collar of the hole, which had heated and had caused one of the downlines to melt.

5. 24/11/17

- Hole D3 was reprimed and stemmed with crushed aggregate
- At 8:30pm hole E2 self-initiated

Incident Location



7

Incident Photo – P16 Blast pattern post incident



Incident Photo – P16 Blast pattern post incident



Investigation

The possible scenarios that could have led to the unplanned initiation that were considered and analysed were:

- Spontaneous combustion of coal causing heating of explosive product
- A reaction between either reactive waste or coal and the explosive product
- A reaction between either waste or coal and the explosive product contributed to by the product being the last remaining emulsion from the tanks
- Hot ground causing explosive product to heat
- Movement along a strata plane impacting a detonator
- Spillage of diesel on bench causing increased volatility
- Lightning
- Seismic activity
- "Slap Snap Shoot"
- Sabotage

Investigation Findings – Contributing Factors

- 1) There was a lack of appreciation for the risk posed by reactive ground
- Reactive ground test drilling was not completed in a targeted, structured or timely manner – Samples were taken opportunistically as part of sites coal quality / geotechnical drilling program
- 3) There was no formal process in place at the mine for managing reactive ground
- 4) Results of reactive ground tests were provided to the explosives supplier yet no feedback was received highlighting any concerns
- 5) There was no formal process for routine cleaning of emulsion tanks
- 6) The mine has progressed into an area near the bottom of a syncline where geological conditions may have varied

Key Learnings & Actions

Key Learnings

- 1) Prior history should not be considered a control and, as such, systems must be adequate to capture changing conditions
- 2) Conformance with a code of practice does not necessarily control the hazard. Codes should be used as a guide and referenced as a minimum standard.

Actions

- 1) Sites to demonstrate (or implement) a process of systematic identification and review of the potential for reactive ground, and where identified, that appropriate controls to mitigate the risk are in place
- 2) Incorporate reactive ground into the technical frame work (TFW) by development of a standard/ protocol and incorporate into associated health checks. The content is to be aligned to meet the intent of the AEISG Code of Practice (Elevated Temp and Reactive Ground) as a minimum.
- 3) Numerous site actions related to identifying reactive ground areas, sourcing suitable products and updating PHMP / Procedures

- Clermont has been blasting for 10 years without any prior incidents relating to reactive ground
- There is no evidence of any consideration of reactive ground in feasibility studies
- 45 reactive ground tests have been undertaken between 2015 and 2017. These were from a variety of lithology's and depths.

Reactive Ground | MTi Learnings (Common to All Sites)

ISEE Conference | Fremantle November 2018



Introduction

- The Clermont team did not act differently to the vast majority of mines prior to the event. Their sample collection and testing regime was thought to be acceptable.
- The event and respective testing has shown that closer scrutiny should be given to certain rock types that may have been excluded in the past.
- The following points are suggestions developed by MTi Laboratory Testing Pty Ltd.



Prevention

- Use the AEISG code safety factors as a minimum guideline only
- Undertake a geological risk assessment (risk ranking exercise) consider outside assistance if understanding of Reactive Ground is lacking on site.
- Test at least the minimum samples for each rock type
- Each year collect and test multiple samples (over and above AEISG)
- Base further sampling on the test results and the risk ranking exercise



Risk Management

Understanding Reactivity Determined by the code

- Ensure that mine geologists have an understanding of the sulphide mineralogy of all rock types on site.
- Use additional test methods to determine sulphide minerology of samples
- Reactivity needs to be understood to obtain an optimal safe and effective blasting solution
- Utilise industry best practice procedures
- Utilise competency based training
- Regularly review/audit competency



We got a free lesson

Key message – If your site believes they do not have reactive ground, go and check there is data behind the belief